25X1

25**X**1

25X1

SECRET

TILE INFO (When Filled In)

FILE INFO		(17/10/17/17/03/17/						
1 0 Dec 71 3	8843	REPRODUCTION PROHIBITED				1 2 1		
ACTION	1	00	6	0/005	11	Ce	16	
	2	1	7	TWIEL	12		17	
	3	7 .	8	Twose L	13		18	
	4	LUA	9	IDEA	14		19	
	5	RB	1ø	1.	15		2ø	

NNNS E C R E T 101600Z DEC 71 CITE 4315

PRIORITY

IDEALIST/W - DM-4

REC.107 \$ B.

25X1 REF: A. DTD 8 DEC 71

DTD 8 DEC 71- mission C-361-C

SUBJ: RFI " H" CONFIG

- 1. PERIODIC NOISE OF 16 SEC ON 1 SEC OFF DOES NOT CORRESPOND TO ANY RECOGNIZED CYCLE IN H CONFIG.
- 2. REF A REPORTS HIGH NOISE AT Ø451, Ø459 AND Ø5Ø4. REF B

 NOTES H CONFIG IN MODE 1 FROM Ø426 TO Ø5Ø5. IN THIS

 MODE CONFIG IS UNCAGED BUT NOT CYCLING. NOISE IN THIS NON-OPERATE

 MODE WOULD BE SURPRISING.
 - 3. AS WE READ REF A PARA 5, THE NOISE WENT AWAY AT 0543. PER REF B THE "H" CONFIG TURNED TO MODE OFF AT 0548. IS THIS CORRECT? PLEASE ADVISE.
- 4. NEW LIGHT WEIGHT "H" MOUNT HAS A GROUND STRAP FROM GIMBAL HOUSING WHICH IS TO BE CONNECTED TO VEHICLE. THE GROUND STRAP LUG SHOULD BE NEXT TO VEHICLE AT MOUNT ATTACH POINT AND SECURED WITH MOUNT BOLT. IT MIGHT BE NECESSARY TO CLEAN UP ATTACH POINT.

SECRET

BT